



# Product Discontinuation Notification

Document availability: **Public**

## Title: Discontinuation of IDS cameras with onsemi MT9P031 sensors

<b>Affected Product:</b>	IDS uEye cameras (detailed list of models in document)
<b>Document Version:</b>	1.01 Changes: More detailed version naming affected cameras. Replaces former version 1.00 of this document from 16 <sup>th</sup> February 2023
<b>Release date:</b>	March 6 <sup>th</sup> 2023

## Reasons and Description of the Product Discontinuation

The supplier of the imaging sensors built into the affected IDS cameras, onsemi, decided to discontinue the production of the imaging sensors MT9P031I12STC-DP and MT9P031I12STM-DP by end of March 2023. For this reason, IDS has to announce the discontinuation of the camera models listed below.

Last-time-buy orders for cameras with the above mentioned onsemi MT9P031 sensors can be placed.

## Recommended action for customers

IDS recommends that all customers of the models listed below promptly place their last-time-buy order with an appropriate volume covering the life span of the related customer projects or devices.

IDS has already taken action and provides alternative camera models.

For any question regarding last-time-buy orders or successor models, please contact our sales team.

## Important Dates

End of Sale	Last Shipment Date	End of Support
15 <sup>th</sup> March 2023	15 <sup>th</sup> September 2023	15 <sup>th</sup> June 2026

## Affected Part Numbers List

Part Number			
GV-548x	UI-148x	UI-348x	UI-548x
AB02031	AB.0010.1.23100.12	AB00360	AB00105
AB12031	AB.0010.1.28900.00	AB00043	AB.0010.1.55800.24
AB22031	AB00522	AB01002	AB00034
AB02329	AB.0010.1.34200.23	AB00520	AB.0010.1.55700.23
AB12329	AB02624	AB01352	AB00652
AB02323	AB.0010.1.34200.00	AB00641	AB00111
AB12323	AB00595	AB03078	AB02044
AB01283	AB03212	AB00878	AB01216
AB11283	AB.0010.1.23100.23	AB00485	AB01317
AB21283	AB.0010.1.23100.00	AB01235	AB12044
AB02324	AB.0010.1.33600.25	AB00491	AB11216
AB12324	AB.0010.1.33600.23	AB01273	AB11317
AB02325	AB00579	AB02223	AB.0010.1.55700.24
AB12325	AB00591	AB00487	AB.0010.1.55700.56
	AB.0010.1.33600.00	AB01492	AB02313
	AB.0010.1.29000.23	AB02541	AB12313
	AB.0010.1.29000.00	AB00489	1007750
	AB.0010.1.34300.23	AB01034	1008519
	AB00036	AB.0010.1.28900.28	AB10305
	AB02625	AB.0010.1.23100.28	AB10306
	AB.0010.1.34300.00	AB.0010.1.29000.28	AB00703
	AB.0010.1.24700.00	AB.0010.1.34200.28	AB.0010.1.37302.12
	AB00217	AB.0010.1.34300.28	AB.0010.1.37302.24
	AB.0010.1.36600.23	AB.0010.1.33600.28	AB.0010.1.37402.25
	AB.0010.1.29200.00	AB00141	AB.0010.1.37402.12
	AB.0010.1.34500.00	AB02511	AB.0010.1.37402.23
	AB02613		AB00165
	AB03576		AB00016
	AB01014		AB12307
	AB01040		AB.0010.1.37402.24
	AB01058		AB10447
	AB01022		AB12213
			AB.0010.1.65500.23
			AB12308
			AB10449
			AB12214
			AB00102



# Product Discontinuation Notification

Part Number			
GV-548x	UI-148x	UI-348x	UI-548x
			AB00013
			AB02309
			AB12309
			1007472
			AB01069
			AB10468
			AB02215
			AB12215
			AB10526
			AB.0010.1.37302.28
			AB00025
			AB.0010.1.37402.28
			AB00024
			AB00078